Professional Service Industries, Inc.
2020 North Loop 499, Suite 302
Harlingen, TX 78550
Texas Firm Registration No. F-03307
Phone: (956) 423-6826
Fax: (956) 423-5735

Report No: MAT:03283290-40-S4
Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Material Test Report

Client: SPACELAND INVESTMENTS LLC
2133 SANTA ANA AVE
RANCHO VIEJO, TX 78575

CC: JORGE ALANIS
JUAN CELIS
MARCO ZERTUCHE
MARK SALDANA
SAUL YANEZ

Project: RIVERWOOD SUBDIVISION
BROWNSVILLE,, TX

Approved Signatory: Mathew Aguirre (Project Specialist)
Date of Issue: 9/25/2026

Sample Details

Sample ID:	03283290-40-S4	**Lift:**	
Client Sample ID:		**Contractor:**	
Date Sampled:	09/23/26		
Sampled By:	Client		
Specification:			
Supplier:	AMR Pit - Brownsville, TX.		
Source:	AMR Pit - Brownsville, TX.		
Material:	Med Brown Sandy Lean Clay (CL)		
Sampling Method:	By Contractor		
Soil Description:	Select Fill		
General Location:	Bucket #4		
Location:	PSI sample id 18885		

Other Test Results


Description	Method	Result	Limits
Cu	ASTM D2487		
Cc			
Procedure	ASTM C117	A	
Group Code	ASTM D2487	CL	
Group Name		Sandy lean clay	
Tested By		Oscar Trejo Jacobo	
Date Tested		9/24/2026	
Liquid Limit	ASTM D4318	33	
Plastic Limit		16	
Plasticity Index		17	
Tested By		Oscar Trejo Jacobo	
Date Tested		9/24/2026	

Particle Size Distribution

Method: ASTM C136
Drying By: Oven
Date Tested: 9/24/2026
Tested By: Oscar Trejo Jacobo

Sieve Size	% Passing	Limits
No.4 (4.75mm)	100	
No.200 (75µm)	68	

Chart



Comments

N/A

© 2000-2026 QESTLab by SpectraQEST.com